



CREEK RELEASE EMERGENCY RESPONSE

KINGFISHER COUNTY, OKLAHOMA
MARCH 2022

Rose Rock responded to a call about a release into a creek in Kingfisher County from a midstream company. A pipeline had been hit by a third party which caused a release of hydrocarbons, impacting Kingfisher Creek. Rose Rock was on site within the hour, assessed the area, and took immediate action to contain the release, including by the use of both absorbent and hard booms, in order to prevent the release from flowing further downstream. Our team also flushed the banks of the creek with fresh water to loosen oil from the vegetation and rocks, cut and bagged impacted vegetation and debris, and transported the impacted materials to a state permitted disposal facility. Rose Rock worked alongside the Oklahoma Corporation Commission and the Oklahoma Department of Wildlife Conversation and documented all findings into a project summary report for the client's records.



Consulting • **Field Services** • Products

Spill Response • Waste Management • Facility Decontamination • Site Investigations • Transportation Services

ROSE ROCK
ENVIRONMENTAL SERVICES

P.O. Box 721926 • Oklahoma City, OK 73172 • (405) 883-1095 • RoseRockEnv.com