




# COMPRESSOR STATION RELEASE REMEDIATION

ROGER MILLS COUNTY, OKLAHOMA  
SEPTEMBER 2022

Rose Rock provided remediation services to a natural gas company in western Oklahoma. Our team analyzed the site and began cleanup efforts by tilling the impacted area and treating it with our in-house remediation agent EcoGreen. Once treated, the area was backfilled with fresh gravel. A portion of the release had extended beyond the fenced area of the site and onto a neighboring land. After treatment, Rose Rock personnel collected soil samples from this area at varying depths and sent the samples to a state-certified laboratory to ensure the area had been properly remediated. Once results were received confirming the treatment was successful, Rose Rock sent the client a project report detailing the process and included full laboratory results.



Consulting • **Field Services** • Products

**Spill Response** • Waste Management • Facility Decontamination • Site Investigations • Transportation Services

**ROSE ROCK**<sup>TM</sup>  
ENVIRONMENTAL SERVICES

P.O. Box 721926 • Oklahoma City, OK 73172 • (405) 883-1095 • [RoseRockEnv.com](http://RoseRockEnv.com)