



# REMEDIATION OF HISTORICAL RELEASE

LEA COUNTY, NEW MEXICO  
MARCH 2022

Rose Rock was retained by an oil and gas operator to provide soil remediation services for a historical release at one of their sites. Rose Rock reviewed all historical data for the site and conducted a site visit to prepare a remediation plan for the client. Our team then began remediation efforts and excavated the impacted area to a depth of four feet and transported the soil off site and disposed of it properly at a state permitted facility. After excavation was completed, soil samples were taken to be analyzed and to confirm that all impacted soil had been removed. Two liners were then installed and the excavated area was backfilled with clean, new soil and compacted to existing grade.



Consulting • **Field Services** • Products

**Spill Response** • Waste Management • Facility Decontamination • Site Investigations • Transportation Services

**ROSE ROCK**<sup>™</sup>  
ENVIRONMENTAL SERVICES

P.O. Box 721926 • Oklahoma City, OK 73172 • (405) 883-1095 • [RoseRockEnv.com](http://RoseRockEnv.com)