

SALTWATER REMEDIATION

Canadian County, Oklahoma July 2021

Rose Rock provided saltwater remediation services for an oil and gas production company in central Oklahoma. Our qualified team assessed the site, sampled the soil for total soluble salts (TSS), and then sent the samples to be analyzed by a state certified, independent laboratory. Once we received the testing results, we began to excavate the impacted area to depth and applied our biodegradable saltwater spill remediation product, Salt Remediator, at the base. In order to avoid the need to haul off all of the excavated soil, we treated it in layers while backfilling the area. This process helped our client save money by removing transportation and disposal service needs from the project. Once the area was completely treated and all soil reapplied, we then provided a watering treatment. Due to the lack of natural rainfall, we continued to provide watering treatments on a bi-monthly basis in the months that followed. The remediation efforts were successful and the project was brought to a close.





Consulting • Field Services • Products

Spill Response • Waste Management • Facility Decontamination • Site Investigations • Transportation Services

