




SOIL REMEDIATION SERVICES

CARTER COUNTY, OKLAHOMA

AUGUST 2022

Rose Rock provided soil remediation services to an oil and gas production company in Carter County, Oklahoma. The remediation area was approximately 12,000 square feet and was excavated one foot in depth. The impacted materials were properly collected and transported to a state permitted disposal facility. Rose Rock personnel then backfilled the affected area with clean, fresh soil. Copies of the disposal manifest, a complete project report, and photos were all provided to the client upon completion of the project.



Consulting • **Field Services** • Products

Spill Response • Waste Management • Facility Decontamination • Site Investigations • Transportation Services

ROSE ROCK[™]
ENVIRONMENTAL SERVICES

P.O. Box 721926 • Oklahoma City, OK 73172 • (405) 883-1095 • RoseRockEnv.com