



OIL AND GAS PRODUCTION SITE REMEDIATION

GRADY COUNTY, OKLAHOMA
NOVEMBER 2022

Rose Rock provided remediation services for a release that occurred at an oil and gas production site. Rose Rock's response team utilized a heated power washer, EcoGreen, and absorbent booms to remediate the release. Rose Rock then collected samples at varying depths and sent them to a state-certified laboratory to be analyzed. Once results were received, Rose Rock returned to the site for further treatment. The impacted areas were tilled and treated with a mixture of EcoGreen and Salt Remediator and impacted equipment on the site were power washed. Once completed, all impacted absorbent materials were collected, containerized, and transported offsite to be properly disposed of. Rose Rock later returned to the site to resample the area and the results confirmed that the EcoGreen and Salt Remediator treatment had been successful.



Consulting • Field Services • **Products**

Eco Degreaser • **EcoGreen** • Eco Rock Cleaner • Paraffin Solvent • **Salt Remediator** • Spill Kits

ROSE ROCK
PRODUCTS

P.O. Box 721926 • Oklahoma City, OK 73172 • (405) 883-1095 • RoseRockEnv.com