



COMPRESSOR STATION REMEDICATION

HEMPHILL COUNTY, TEXAS

JUNE 2022

Rose Rock responded to a release that occurred at a compressor station for a midstream company outside of Canadian, Texas. A vacuum truck was deployed and used to suck up all free standing liquid from the impacted area. A total of 10 barrels of fluid were collected and transported offsite to be disposed of properly. The compressor station equipment and surrounding impacted area were then cleaned with EcoGreen, Rose Rock's in-house remediation agent, via a heated power washer to fully remediate the site.



Consulting • Field Services • **Products**

Eco Degreaser • **EcoGreen** • Eco Rock Cleaner • Paraffin Solvent • Salt Remediator • Spill Kits

ROSE ROCK
PRODUCTS

P.O. Box 721926 • Oklahoma City, OK 73172 • (405) 883-1095 • RoseRockEnv.com