




SUB-SLAB FLUSHING & RECOVERY OF NO. 2 FUEL OIL

HUDSON VALLEY, NEW YORK
AUGUST 2020

A number two fuel oil release occurred from an exterior tank of a residence, contaminating the soils surrounding the tank as well as under the adjacent basement floor slab. The excavatable soil was removed for offsite disposal and a remediation plan was put in place for the remaining areas. Through a series of holes and PVC injection points, a 3% solution of EcoGreen was flushed underneath the slab and all fluids were directed toward a collection point in the basement sump for recovery and disposal. Approximately 2,000 gallons of EcoGreen solution were injected under the basement floor slab over the course of two flushes. Efficacy screening and soil samples were collected after the remediation, confirming that the EcoGreen treatment had been successful in both the remediation and in vapor suppression. In total, over 8,000 gallons of the oily water mixture were collected and transported offsite to be properly disposed of.



Consulting • Field Services • **Products**

Eco Degreaser • **EcoGreen** • Eco Rock Cleaner • Paraffin Solvent • Salt Remediator • Spill Kits

ROSE ROCK
PRODUCTS

P.O. Box 721926 • Oklahoma City, OK 73172 • (405) 883-1095 • RoseRockEnv.com