



OIL AND GAS PRODUCTION SITE REMEDIATION

GRADY COUNTY, OKLAHOMA
NOVEMBER 2022

Rose Rock provided remediation services for a release that occurred at an oil and gas production site. Rose Rock's emergency response crew utilized a heated power washer, Eco Green, and absorbent booms to contain and remediate the released production water and oil. Rose Rock then collected samples at varying depths and sent them to a laboratory to be analyzed. Once results were received, Rose Rock returned to the site for further treatment. The impacted areas were tilled and treated with a mixture of Eco Green and Salt Remediator and equipment on site was power washed. Once completed, all impacted absorbent materials were collected, containerized, and transported offsite to be properly disposed of. Rose Rock later returned to the site to resample the area and confirmed that the remediation had been successful.



Consulting • **Field Services** • Products

Spill Response • Waste Management • Facility Decontamination • Site Investigations • Transportation Services

ROSE ROCK
ENVIRONMENTAL SERVICES

P.O. Box 721926 • Oklahoma City, OK 73172 • (405) 883-1095 • RoseRockEnv.com