



PRODUCTION FACILITY REMEDIATION

KINGFISHER COUNTY, OKLAHOMA
JANUARY 2023

Rose Rock provided remediation services at a production facility in Kingfisher, Oklahoma. Rose Rock excavated the area and all impacted materials were stockpiled on plastic sheeting. Rose Rock then collected samples throughout the site and sent them to a laboratory to be analyzed. Once results were received confirming that the remediation had been successful, Rose Rock returned to the site to backfill the excavated area with crusher run gravel. All collected materials were then transported offsite to be disposed of properly. Once the project was complete, Rose Rock provided a written report to the client including full laboratory analytics, photos documenting the remediation process, and the completed waste manifests for their records.



Consulting • **Field Services** • Products

Spill Response • Waste Management • Facility Decontamination • Site Investigations • Transportation Services

ROSE ROCK
ENVIRONMENTAL SERVICES

P.O. Box 721926 • Oklahoma City, OK 73172 • (405) 883-1095 • RoseRockEnv.com