



PRODUCTION FACILITY SITE REMEDIATION

McCLAIN COUNTY, OKLAHOMA
JANUARY 2023

Rose Rock was retained to provide remediation services at a production facility in Newcastle, Oklahoma. Rose Rock's response team removed all freestanding fluid from the release and the materials within the impacted area were removed and stockpiled for disposal. The area was then treated with Eco Green, Rose Rock's in-house remediation agent. All of the impacted materials were then transported offsite and disposed of properly. For a separate impacted area that stretched to the nearby roadway, absorbent booms were placed and it was flushed with fresh water. After the area had been successfully flushed, the water was collected and transported offsite to be disposed of properly. The area was then tilled and treated with Eco Green. Once the site had been fully remediated, a written report was provided to the client detailing the process and included photos and the completed waste manifest.



Consulting • **Field Services** • Products

Spill Response • Waste Management • Facility Decontamination • Site Investigations • Transportation Services

ROSE ROCK
ENVIRONMENTAL SERVICES

P.O. Box 721926 • Oklahoma City, OK 73172 • (405) 883-1095 • RoseRockEnv.com