



PHOSPHATE DIP TANK CLEANING

OKLAHOMA COUNTY, OKLAHOMA
APRIL 2023

Rose Rock was retained by a global oil and gas manufacturing company to provide industrial cleaning services for their facility in Oklahoma City. A dip tank located inside their facility had been coated in phosphoric acid and needed to be drained and cleaned. All freestanding liquid was first vacuumed and containerized. Rose Rock's crew then began removing the caked-on solid sediment from the floor and all walls until the pit had been successfully cleaned. All collected materials were then collected and containerized in order to be properly disposed of.



Consulting • **Field Services** • Products

Spill Response • **Waste Management** • **Facility Decontamination** • Site Investigations • Transportation Services

ROSE ROCK
ENVIRONMENTAL SERVICES

P.O. Box 721926 • Oklahoma City, OK 73172 • (405) 883-1095 • RoseRockEnv.com