




DAF UNIT CLEANING

OKLAHOMA COUNTY, OKLAHOMA
MAY 2023

Rose Rock provided industrial cleaning services for a water purification company located in Oklahoma City. The company's dissolved air flotation (DAF) units had become caked in oily grease and required an in-depth cleaning. Rose Rock's crew power washed the units with a 3% solution of EcoGreen, Rose Rock's in-house remediation agent, at the client's facility. A sample of the oily sludge was collected and sent to a laboratory to be analyzed in order to certify that it was a nonhazardous substance. All rinse water remaining from the cleaning process was then collected and transported offsite to be disposed of properly.



Consulting • **Field Services** • Products

Spill Response • Waste Management • **Facility Decontamination** • Site Investigations • Transportation Services

ROSE ROCK
ENVIRONMENTAL SERVICES

P.O. Box 721926 • Oklahoma City, OK 73172 • (405) 883-1095 • RoseRockEnv.com