

DAF UNIT CLEANING

Oklahoma County, Oklahoma May 2023

Rose Rock provided industrial cleaning services for a water purification company located in Oklahoma City. The company's dissolved air flotation (DAF) units had become caked in oily grease and required an in-depth cleaning. Rose Rock's crew power washed the units with a 3% solution of EcoGreen, Rose Rock's in-house remediation agent, at the client's facility. A sample of the oily sludge was collected and sent to a laboratory to be analyzed in order to certify that it was a nonhazardous substance. All rinsate remaining from the cleaning process was then collected and transported offsite to be disposed of properly.





Consulting • Field Services • **Products** Eco Degreaser • **EcoGreen** • Eco Rock Cleaner • Paraffin Solvent • Salt Remediator • Spill Kits



P.O. Box 721926 • Oklahoma City, OK 73172 • (405) 883-1095 • RoseRockEnv.com